

EMERALD COAST UTILITIES AUTHORITY
BID NUMBER: 2018 12
ANNUAL WATER WELL MAINTENANCE AND REPAIR CONTRACT
CONTRACT DURATION: ONE YEAR CONTRACT
(WITH TWO ONE-YEAR OPTIONAL EXTENSIONS UPON MUTUAL AGREEMENT
OF BOTH PARTIES, WITH NO INCREASE IN PRICE.)
Bid Opening Date: September 4, 2018 - 2:00 p.m.

ANNUAL WATER WELL MAINTENANCE AND REPAIR			GRINER DRILLING SERVICE, INC SPANISH FORT, AL	LAYNE PENSACOLA, FL	
TASK 1 Site Visit	Site Visit	Lump sum per occurrence	\$ 600.00	\$ 1,350.00	
TASK 2 Removal of Vertical Turbine Pump Assembly	6" Discharge Column Total Length less than 150 ft.	Lump sum per occurrence	\$ 5,400.00	\$ 5,625.00	
	Total Length 150 ft. or more	Lump sum per occurrence	\$ 8,100.00	\$ 8,300.00	
	8" Discharge Column Total Length less than 150 ft.	Lump sum per occurrence	\$ 5,400.00	\$ 5,625.00	
	Total Length 150 ft. or more	Lump sum per occurrence	\$ 8,100.00	\$ 8,300.00	
	10" Discharge Column Total Length less than 150 ft.	Lump sum per occurrence	\$ 8,100.00	\$ 7,625.00	
	Total Length 150 ft. or more	Lump sum per occurrence	\$ 10,800.00	\$ 7,625.00	
	12" Discharge Column Total Length less than 150 ft.	Lump sum per occurrence	\$ 8,100.00	\$ 8,300.00	
	Total Length 150 ft. or more	Lump sum per occurrence	\$ 10,800.00	\$ 10,975.00	
	TASK 3 Video Survey		Lump sum per occurrence	\$ 2,500.00	\$ 1,100.00
	TASK 4 Disassembly of the pump	Size pump less than 15" Size pump 15" or greater	Lump sum per occurrence Lump sum per occurrence	\$ 1,200.00 \$ 1,800.00	\$ 2,000.00 \$ 2,350.00
TASK 5 Rehabilitate or replace pump discharge or suction column sections and/or replace line shaft section					
Item 1 Rehabilitate pump discharge or suction column section	6" discharge column	10 foot section	\$ 340.00	\$ 700.00	
	8" discharge column	10 foot section	\$ 395.00	\$ 900.00	
	10" discharge column	10 foot section	\$ 460.00	\$ 1,150.00	
	12" discharge column	10 foot section	\$ 540.00	\$ 1,450.00	
Item 2 Replace pump discharge or suction column section	6" discharge column	10 foot section	\$ 700.00	\$ 1,250.00	
	8" discharge column	10 foot section	\$ 970.00	\$ 1,600.00	
	10" discharge column	10 foot section	\$ 1,395.00	\$ 2,250.00	
	12" discharge column	10 foot section	\$ 1,655.00	\$ 2,800.00	
Item 3 Replace Line Shaft	1 3/16 shaft size	10 foot section	\$ 210.00	\$ 300.00	
	1 1/2 shaft size	10 foot section	\$ 360.00	\$ 450.00	
	1 15/16 shaft size	10 foot section	\$ 560.00	\$ 725.00	
	2 3/16 shaft size	10 foot section	\$ 765.00	\$ 1,000.00	
TASK 6 Reinsertion of the pump assembly into the well colmn	6" Discharge column and line shaft Total Length less than 150 ft.	Lump sum per occurrence	\$ 5,400.00	\$ 7,225.00	
	Total Length 150 ft. or more	Lump sum per occurrence	\$ 8,100.00	\$ 9,900.00	
	8" Discharge column and line shaft Total Length less than 150 ft.	Lump sum per occurrence	\$ 5,400.00	\$ 7,225.00	
	Total Length 150 ft. or more	Lump sum per occurrence	\$ 8,100.00	\$ 9,900.00	
	10" Discharge column and line shaft Total Length less than 150 ft.	Lump sum per occurrence	\$ 8,100.00	\$ 9,225.00	
	Total Length 150 ft. or more	Lump sum per occurrence	\$ 10,800.00	\$ 9,225.00	
	12" Discharge column and line shaft Total Length less than 150 ft.	Lump sum per occurrence	\$ 8,100.00	\$ 9,900.00	
	Total Length 150 ft. or more	Lump sum per occurrence	\$ 10,800.00	\$ 12,575.00	
TASK 7 Well and pump performance/ efficiency tests		Lump sum per occurrence	\$ 800.00	\$ 1,800.00	
TASK 8 Disinfection		Lump sum per occurrence	\$ 500.00	\$ 4,500.00	
Proposal Signed	Yes/No		YES	YES	
Exceptions	Yes/No		YES	YES	
Addendum Acknowledged	Yes/No		YES	-	