

EMERALD COAST UTILITIES AUTHORITY
BID CC2015 05
CWRF Administration Building and Roof Restoration
January 30, 2015

ADDENDUM NUMBER 6

Prospective Bidders:

This addendum is issued to clarify questions received.

1. On the east elevation 2nd floor balcony there is a detail for removing the coping stone and installing flashing. However, one section of the coping stone is level with the pavers (see attached picture). Are we to just install membrane with no through wall flashing? If needed please supply detail?

Answer: Yes, see attached detail. The intent is to flash under all stone as the water-proofing is deficient. At this condition, the new flashing will tie in with the membrane and will extend and integrate with through-wall flashing of the brick.

2. There are details for work to be done at the head and sill of windows however there is no detail for work to be done to the sills of storefronts on the 2nd floor balcony. Are we to figure on doing any work the sill of any storefront doors or metal doors? If so please provide necessary direction/details for pricing?

Answer: No, the storefront sills rest directly on the slab and do not require any restoration as part of this project.

Please note the attachment. Contractor's Proposal Page 00003-2 is hereby replaced with the attached. **All submittals must use the revised proposal page attached or the submittal will be rejected as non-responsive.**

If you have any questions, please call my office at 850-969-6531, or email me at amy.williamson@ecua.fl.gov.

Regards,

Amy Williamson, CPPB, FCCM
Senior Purchasing Agent