



EMERALD COAST UTILITIES AUTHORITY
BID NUMBER: 2018 13
TRUCK TIRE/RETREAD SERVICES AND SECTION REPAIRS
Bid Opening: August 23, 2018

	ESTIMATED ANNUAL QUANTITY	GOODYEAR AKRON, OH		HOWELL TRUCK & GIANT TIRE PENSACOLA, FL		NEECE TIRE AND AUTO SERVICE TALLAHASSEE, FL		SOUTHERN TIRE MART, LLC COLUMBIA, MS	
Item A: Retread Services		UNIT COST	EXTENDED COST	UNIT COST	EXTENDED COST	UNIT COST	EXTENDED COST	COST	EXTENDED COST
Tire Size									
1) 11R22.5 With Waste Hauler Rib or Equivalent Manufacturer/Model	500	\$122.00	\$61,000.00	\$121.50	\$60,750.00	\$122.00	\$61,000.00	\$126.50	\$63,250.00
		GOODYEAR PRECURE G686 (254086351)		MARANGONI UTWR 24		PC686		BANDAG BRM	
2) 315/80R22.5 With Waste Hauler Rib or Equivalent Manufacturer/Model	100	\$144.00	\$14,400.00	\$142.00	\$14,200.00	\$144.00	\$14,400.00	\$149.46	\$14,946.00
		GOODYEAR PC G686 (254096351)		MARANGONI UTWR 24		PC686		BANDAG BRM	
3) 12R22.5 With Waste Hauler Rib or Equivalent Manufacturer/Model	50	\$130.00	\$6,500.00	\$75.00	\$3,750.00	\$130.00	\$6,500.00	\$136.75	\$6,837.50
		GOODYEAR PC G686 (254087351)		MARANGONI UTWR 24		PC686		BANDAG BRM	
4) 425/65R22.5 With Waste Hauler Rib or Equivalent Manufacturer/Model	30	\$150.00	\$4,500.00	\$75.00	\$2,250.00	\$150.00	\$4,500.00	\$150.93	\$4,527.90
		GOODYEAR PCWIDE BASE RIB (254375984)		MARANGONI RSIY		WIDE BASE RIB		BANDAG BRM	
B. Section Repairs									
1) Small Section Repair (approx. size 3 1/2" x 5 1/4")	128	\$25.00	\$3,200.00	\$12.00	\$1,536.00	\$20.00	\$2,560.00	\$12.00	\$1,536.00
2) Large Section Repair (approx. size 4 1/2" x 8")	50	\$30.00	\$1,500.00	\$17.50	\$875.00	\$35.00	\$1,750.00	\$17.50	\$875.00
SIGNED: YES/NO		YES		YES		YES		YES	
EXCEPTIONS: YES/NO		YES		NO		NO		NO	